

바닥 Marking Tape

통행로 바닥에 부착하여 위험상황을 쉽게 식별할 수 있게 함.

사이즈 : 17"(431mm)



510001



510002



510003



510004



510005



510005



510007



510008



510009



510010



510011



510012



510013



510014



510015



510016



510017



510018



510019



510020

경고
말릴 위험
구동중 접촉금지.
서비스 전 주전원 차단 및 잠금장치 체결할 것.

720046

경고
말릴 위험
구동중 접촉금지.
서비스 전 주전원 차단 및 잠금장치 체결할 것.

720047

WARNING
Entanglement hazard.
Do Not operate with guard removed.
TURN OFF and lockout power before servicing.

720048

경고
돌출물 주의.
발 밑을 조심하십시오.

720049

주의
돌출물 주의.
발 밑을 조심하십시오.

720050

위험
충격 위험
로봇트 작업반경내 접근 금지.

720051

금지
충돌 위험
출입 금지
로봇정지후 출입.

720052

DANGER
Impact hazard.
You must not enter work area of the robot.

720053

경고
협착/말릴 위험
안전 가드 개방 중 작동금지.
운전 중 체인회전부에 접촉금지.

720054

경고
말릴 위험
구동중 접촉금지.
서비스 전 주전원 차단 및 잠금장치 체결할 것.

720055

경고
전단/협착 위험
회전부에 손대지 마시오.
서비스전 사용설명서를 숙지할 것.

720056

경고
절단 위험
작업중 접근금지.

720057

WARNING
Crush hazard.
Hard hats must be worn in this area.

720058

경고
협착/말릴 위험
안전 가드 개방 중 작동금지.
운전 중 벨트회전부에 접촉금지.

720059

경고
협착 위험
구동 중 접촉금지.

720060

WARNING
Fall hazard.
Do Not Climb on the machine.

720061

WARNING
Pinch point.
keep hands clear of rollers.

720062

경고
고온/협착 위험
구동중 접촉 금지.
서비스 전 주전원 차단 및 잠금장치 체결할 것.

720063

WARNING
Hot surface crush hazard.
Keep hands clear.
TURN OFF and lockout power before servicing.

720064

WARNING
Pinch point.
keep hands clear of rollers.

720065



720066



720067



720068



720069



720070



720071



720072



720073



720074



720075



720076



720077



720078



720079



720080



720081



720082



720083



720084



720085



720086



720087



720088



720089



720090



720091



720102